


100




FIRST  
OPERATING  
PARAMETER

SECOND  
OPERATING  
PARAMETER

Fig. 1  
Prior Art

250

StartPoint=( 1.95000, 3.50000))  
 HorizontalStepSize= 0.05000 VerticalStepSize= 0.05000  
 HorizontalRange - 1.00000 - 2.60000 VerticalRange - 2.00000 - 4.60000



Second  
Operating  
Parameter  
220

1 1 1 1 1 1 1 1 1 2 2 2 2 2 2 2 2  
 . . . . . . . . . . . . . . . . . .  
 5 5 6 6 7 8 8 9 9 0 0 1 1 2 2 3 3 4  
 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0 5 0 5  
 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

First Operating Parameter

Points Tested - 130

210

Fig. 2

10025039 12004





Fig. 3



400








Fig. 4